



### SPARE PARTS

– MEASURING CONTACT FOR  
MOVEABLE MEASURING ARM  
ORDER NO.: 1530/14

SCALE: 1:1  
SUBJECT TO TECHNICAL ALTERATIONS

TYPE: Pocotest  
RANGE OF APPLICATION: 0–10mm  
SCALE INTERVAL: 0.01mm

ACCEPTABLE DEVIATIONS:  
TOTAL MEASURING RANGE  $f_M = \pm 0.1\text{mm}$   
PARTIAL MEASURING RANGE  $f_f = \text{---}$   
REPEATABILITY  $f_w = 0.05\text{mm}$

MEASURING FORCE: 0.3–1.3N  
WEIGHT: ca. 40g

REFERENCE TEMPERATURE: 20°C  
OPERATION TEMPERATURE: 10°C–30°C  
STORAGE TEMPERATURE: –10°C–50°C